05&S'S



Chill C.I. Patt. 51-160 A
Change 51-160
NOT USED ON #1 FURNACE



Washer - Cast Iron Patt. 51-156



Bevel Chill - Cast Iron, Taken from Stock
Patt. not made



Chill - Cast Iron Patt. 51.160

NOTE:- SEE SK-51876
FOR NEW PATT. 51-443



CHILL C.I. PATT. 51-159



Skew Back - Cast Iron Patt. 51-157

NOT USED IN 1929 ALTERATION



Plan View Pit Fce. #1
IN 1929 ALTERATION ARCH REPLACED WITH
BEAMS & STEEL COLS. SEE DWG. S-29784



Section Showing Arch



Blank flange for burn-out pipe
W.I. Mark B.

Burn-out Elbow - Cast Iron Patt. 51-158



Tie Bolt Mark A
Steel



Water Box.
Cast Iron Patt. No. S.I.151 Shown by full lines.
" " Patt No S.I.151 A " " broken "

Pit Furnace No. 1.
Details of Water Box etc.
Bessemer Works — N.I. and S.C.
Youngstown O. July 28 1902.
Scale 1" = 1'-0"

S-5630

B-1128
10-8-29 M.C.

Revised Nov. 3-09
Revised Sept. 2-10